

# Mill Pond Dam

## Visual Inspection Report

Durham, New Hampshire

Dam #071.03

Date of October 13, 2021



**TABLE OF CONTENTS**

|   | <u>Page No.</u> |
|---|-----------------|
| <b>1.0 DESCRIPTION OF PROJECT</b>                 | <b>1</b>        |
| 1.1 General.....                                  | 1               |
| 1.1.1 Authority                                   | 1               |
| 1.1.2 Purpose of Work                             | 1               |
| 1.1.3 Common Dam Safety Definitions               | 1               |
| 1.2 Description of Project.....                   | 1               |
| 1.2.1 Location                                    | 1               |
| 1.2.2 Owner/Caretaker                             | 2               |
| 1.2.3 Purpose of the Dam                          | 2               |
| 1.2.4 Description of the Dam and Appurtenances    | 2               |
| 1.2.5 Operations and Maintenance                  | 2               |
| 1.2.6 Hazard Potential Classification             | 2               |
| 1.3 Engineering Data .....                        | 3               |
| 1.3.1 Discharges at the Dam Site                  | 3               |
| 1.3.2 General Elevations (feet)                   | 3               |
| 1.3.3 Primary Spillway                            | 3               |
| 1.3.4 Low-Level Outlet                            | 3               |
| 1.3.5 Fish Ladder                                 | 3               |
| 1.3.6 Construction Records                        | 4               |
| 1.3.7 Operations Records                          | 4               |
| <b>2.0 INSPECTION</b>                             | <b>5</b>        |
| 2.1 Visual Inspection .....                       | 5               |
| 2.1.1 General Findings                            | 5               |
| 2.1.2 Embankment Abutments                        | 5               |
| 2.1.3 Primary Spillway                            | 6               |
| 2.1.4 Gated Outlet Structure                      | 16              |
| 2.1.5 Fish Ladder                                 | 18              |
| 2.1.6 Downstream Area                             | 19              |
| 2.1.7 Reservoir Area                              | 19              |
| 2.2 Caretaker Interview .....                     | 19              |
| 2.3 Operation and Maintenance Procedures .....    | 19              |
| 2.3.1 Operational Procedures                      | 19              |
| 2.3.2 Maintenance of Dam and Operating Facilities | 19              |
| <b>3.0 ASSESSMENTS</b>                            | <b>21</b>       |
| 3.1 Assessments.....                              | 21              |
| 3.2 Current Hazard Potential Classification ..... | 22              |
| 3.3 Hydraulic/Hydrologic Data .....               | 22              |
| 3.4 Structural and Seepage Stability.....         | 22              |
| 3.4.1 Structural Stability of Dam                 | 22              |
| 3.4.2 Seepage Stability                           | 23              |



ATTACHMENTS:

- Figure 1: Locus Plan
- Figure 2: Aerial Plan
- Figure 3: Site Sketch
- Appendix A: Spillway Cell Inspection Figures
- Appendix B: Photographs
- Appendix C: Common Dam Safety Definitions
- Appendix D: References and Resources
- Appendix E: Visual Dam Inspection Limitations



## 1.0 DESCRIPTION OF PROJECT

### 1.1 General

#### 1.1.1 Authority

The Town of Durham has retained Pare Corporation of Foxboro, Massachusetts, working under subcontract to VHB, Inc., to perform a visual inspection and develop a report of conditions for the dam at Mill Pond along the Oyster River in Durham, New Hampshire. This inspection and report were performed in general accordance with the New Hampshire Department of Environmental Services Env-Wr 100-700 Dam Rules.

#### 1.1.2 Purpose of Work

The purpose of this investigation was to inspect and document the present condition of the dam and appurtenant structures in accordance with current dam safety regulations to provide information that will assist in both prioritizing dam repair needs and planning/conducting maintenance and operation.

The investigation was divided into three parts: 1) obtain and review available files including reports, investigations, and data pertaining to the dam and appurtenant structures; 2) perform a visual inspection of the site; and; 3) prepare and submit a final report presenting the evaluation of the structure.

#### 1.1.3 Common Dam Safety Definitions

To provide the reader with a better understanding of the report, definitions of commonly used terms associated with dams are provided in Appendix C. Many of these terms may be included in this report. The terms are presented under common categories associated with dams which include: 1) orientation; 2) dam components; 3) hazard classification; 4) general; and 5) condition rating.

### 1.2 Description of Project

#### 1.2.1 Location

The Mill Pond Dam is located in the Town of Durham, approximately 600 feet southeast of the Durham Town Hall. The dam impounds water along the Oyster River to form Mill Pond. The dam is located at the eastern side of the impoundment near coordinates 43.1305°N/70.9194°W as shown on Figure 1: Locus Plan and Figure 2: Aerial Plan.

The dam is accessible from a vegetated area at the left abutment. There is no parking area at the dam. To reach from dam from I-95N, take exit 6N towards Dover and keep left at the fork to continue toward US-4 W. Follow US-4 W for 4.8 miles and turn left onto US-4W (Boston Harbor Road). Continue straight on US-4 W for 0.2 miles. At the traffic circle take the second exit to continue onto US-4W. Follow US-4 W for 3.4 miles. Take the exit for NH-108 towards Durham/Newmarket and turn left onto NH-108 S/Dover Road. Follow Dover Road for 0.7 miles and turn left onto Newmarket Road. After 0.2 miles, the dam will be on the right.



### 1.2.2 Owner/Caretaker

The dam is currently owned and operated by the Town of Durham. Maintenance for the structure is primarily completed by the Town's Department of Public Works.

### 1.2.3 Purpose of the Dam

The dam currently impounds water for recreational purposes. The dam was originally constructed in 1913 to provide hydropower to the Jenkins Mill that previously existed at the right abutment.

### 1.2.4 Description of the Dam and Appurtenances

The Mill Pond Dam is an approximately 140-foot long concrete dam. The Mill Pond Dam has a maximum structural height of approximately 13 feet. The dam consists of three components: 1) Primary Spillway; 2) Gated Outlets; and 3) Fish Ladder.

The spillway structure for the dam is an approximately 100-foot wide reinforced concrete modified Ambursen type buttress dam. The spillway consists of a reinforced concrete shell supported by reinforced concrete ribs spaced approximately 12 feet on center beneath the crest. Flow over the spillway discharges into a bedrock plunge pool before discharging beneath the bridge carrying Newmarket Road/NH-108.

The gated outlets are located at the right end of the dam and consists of two 4-foot wide timber gate controlled bays. The gate operators consist of rack and pinion type operators with timber gate stems. The right-most gate structure was previously used to supply the mill downstream with hydropower and is currently not utilized; the left gate structure is presently used as the low level outlet. Flows from the low-level outlet enter the gate structure and outlet to the downstream channel where the masonry structure for the previous mill foundations are located.

A Denil (baffle) fishway is located at the left end of the dam.

### 1.2.5 Operations and Maintenance

The Town of Durham is responsible for operations and maintenance at the dam. Operations at the dam include the operation/exercising of the gate. Maintenance activities at the dam include cutting of vegetation along at the abutments.

### 1.2.6 Hazard Potential Classification

In accordance with current classification procedures under State of New Hampshire Dam Rules, Mill Pond Dam is currently classified as a **Low** hazard potential dam.



### 1.3 Engineering Data

#### 1.3.1 Discharges at the Dam Site

No records of discharges at the dam site were made available during the preparation of this report.

#### 1.3.2 General Elevations (feet)

Elevations are based upon a survey completed by VHB in December 2019 and January 2020. Elevations reference the NAVD88 vertical datum.

|                                 |            |
|---------------------------------|------------|
| A. Top of Dam                   |            |
| i. Left abutment:               | 15.5 ft ±  |
| ii. Right Abutment:             | 12.9 ft ±  |
| B. Normal Pool (Spillway Crest) | 10.85 ft ± |
| C. Maximum Pool                 | 12.89 ft ± |

#### 1.3.3 Primary Spillway

|                             |  |
|-----------------------------|--|
| A. Type                     | Broad Crested Weir (Ambursen type dam) |
| B. Width                    | 100 ft ±                               |
| C. Spillway Crest Elevation | 10.85 ft ±                             |

#### 1.3.4 Low-Level Outlet

|                      |                               |
|----------------------|-------------------------------|
| A. Type              | Gate Controlled Structure     |
| B. Conduit           |                               |
| i. Right             | 18-inch Steel Pipe (corroded) |
| ii. Left             | 48-inch Wide Concrete Opening |
| C. Right Gate Invert |                               |
| i. In                | Unknown                       |
| ii. Out              | 0.8 ft ±                      |
| iii. Outlet Diameter | 18 inches ±                   |
| D. Left Gate Invert  |                               |
| i. In                | Unknown                       |
| ii. Out              | 1.7 ft ±                      |
| iii. Outlet Size     | 4 ft by 6 ft ±                |
| E. Outlet Control    | Two Gates of unknown size     |

#### 1.3.5 Fish Ladder

|           |                |
|-----------|----------------|
| A. Type   | Denil (Baffle) |
| B. Width  | 4 feet         |
| C. Invert |                |
| i. In     | 12.2 ft ±      |
| ii. Out   | 0.1 ft ±       |



### **1.3.6 Construction Records**

The Mill Pond Dam was constructed in 1913 to replace the last of a series of timber dams that provided hydropower. The Mill Pond Dam provided hydropower to the Jenkins Mill when it was first built. No construction documents were available for review.

The Mill Pond Dam was repaired in 1974. No construction documents were available for review. Repairs to the dam in 1974 consisted of:

- Repairs to the concrete within the cells of the spillway.
- Construction of the fish ladder at the left abutment.
- Reconstruction of the downstream edge of the spillway crest

### **1.3.7 Operations Records**

No operations records are available or known to exist for this structure.



## 2.0 INSPECTION

### 2.1 Visual Inspection

Mill Pond Dam was inspected on October 13, 2021. At the time of the inspection, temperatures were near 75°F with clear skies. Photographs to document the current condition of the dam were taken during the inspection and are attached at the end of this report.

To facilitate inspection of the spillway, the Durham DPW implemented a shallow drawdown of the impoundment through opening of the left gated outlet. The drawdown lowered the level of the impoundment approximately 1 to 2 inches with the pool level slowly rising as the inspection was completed.

Underwater areas were not inspected as part of the field activity.

#### 2.1.1 General Findings

In general, the overall condition of the Mill Pond Dam was found to be **Poor** condition. The specific observations are identified in more detail in the sections below.

#### 2.1.2 Embankment Abutments

The following was noted along the left and right embankment abutment.

##### Left Embankment Abutment

| Current Observations  |
|---|
| <ul style="list-style-type: none"> <li>➤ The left abutment consists of well-maintained grass cover.</li> <li>➤ Two drainage valleys are present on the downstream side of the left embankment abutment. One being parallel to the downstream bridge, and the other parallel to the fish ladder. The valleys are generally stable with no significant erosion noted.</li> <li>➤ Trees and brush were present along the upstream side of the abutment left of the fish ladder.</li> <li>➤ Brush growth with small tree development was present on the downstream side of the abutment between the downstream fish ladder and the downstream bridge abutments.</li> <li>➤ The downstream stone wall left of the fish ladder is overgrown with vines and small brush.</li> <li>➤ Erosion is present along the shoulder of the left embankment and the downstream stone wall.</li> <li>➤ Vertical and horizontal irregularities are typical throughout the left abutment.</li> </ul> |

##### Right Embankment Abutment

| Current Observations   |
|--|
| <ul style="list-style-type: none"> <li>➤ A large portion of the right embankment abutment is made up of the backyard of a residential home consisting of an asphalt drive, cobblestone, and a grass area.</li> <li>➤ The upstream right embankment consists of a well-maintained grass cover.</li> <li>➤ Minor soil erosion was present behind the concrete cap of the wall.</li> <li>➤ The downstream side of the right embankment is overgrown with brush and trees immediately left of the asphalt paved driveway.</li> </ul> |





### 2.1.3 Primary Spillway

For the purposes of the report, inspection of the spillway was segmented between three distinct components of the spillway including the spillway slab, training walls, and spillway cells (defined as the void space between adjacent ribs).

#### Spillway Slab

| <b>New Observations:</b>   |   |
|--|---|
| <ul style="list-style-type: none"> <li>➤ Minor leaf and stick debris are present along the upstream side and approach of the spillway slab.</li> <li>➤ Moss growth is present on the downstream side of the spillway slab.</li> </ul>  |   |
| <b>Review of Previous Observations</b>   | <b>Comments from Current Inspection</b>   |
| <ul style="list-style-type: none"> <li>➤ While observing the impoundment filling, flow over the spillway started within the left third section of the spillway, indicating the right portion of the spillway is slightly higher than that of the left portion of the spillway. It was not apparent if this was the result of differential settlement, uneven crest scour, or an as-built condition.</li> </ul> | <ul style="list-style-type: none"> <li>➤ Flow was not observed over the spillway at the time of the inspection.</li> </ul>  |
| <ul style="list-style-type: none"> <li>○ Two construction joints were noted on the spillway approximately 30-feet apart. The condition of the construction joints could not be observed due to snow coverage during the drawdown.</li> </ul>   | <ul style="list-style-type: none"> <li>➤ Flowing water was observed through the right construction joint. Both joints were observed to have scour and jagged edges with severe concrete deterioration near the top of the stem adjacent to the joint.</li> </ul>  |
| <ul style="list-style-type: none"> <li>➤ A full inspection of the spillway crest could not be completed due to snow coverage during the drawdown and water flow over the spillway when the pond refilled. Previous reports noted transverse cracks along the crest of the spillway.</li> </ul>   | <ul style="list-style-type: none"> <li>➤ Moss growth was present along the downstream side of the spillway.</li> <li>➤ No cracking was observed along the downstream face of the spillway.</li> <li>➤ Water levels upstream of the spillway prohibited a full viewing of the upstream portion of the spillway.</li> </ul> |
| <ul style="list-style-type: none"> <li>➤ Scour was present along the spillway crest.</li> </ul>  | <ul style="list-style-type: none"> <li>➤ Scour on the spillway crest remains similar to that previously reported.</li> </ul>  |

#### Training Walls

| <b>New Observations:</b>   |   |
|--|---|
| <ul style="list-style-type: none"> <li>➤ Scour was present along the joint between the right training wall and the downstream side of the spillway crest. The scour measured 6-inches deep.</li> <li>➤ An apparent 1/2-inch gap was observed between the spillway and the right spillway training wall. This appears to be an as-built condition.</li> </ul> |   |
| <b>Review of Previous Observations</b>   | <b>Comments from Current Inspection</b>   |
| <ul style="list-style-type: none"> <li>➤ Scour was present at the joint between the right training wall and spillway, measuring 9-inches deep, 12-inches tall, and 5-feet long.</li> </ul>   | <ul style="list-style-type: none"> <li>➤ Scour on the right training appeared similar to that previously reported.</li> </ul>     |
| <ul style="list-style-type: none"> <li>○ Minor scour (less than 1 inch deep) was noted along the water level at the left training near the spillway.</li> </ul>  | <ul style="list-style-type: none"> <li>➤ Scour on the left training wall appeared similar to that previously reported.</li> </ul> |
| <ul style="list-style-type: none"> <li>➤ A spall (approximately 3 feet long) is located at the</li> </ul>  | <ul style="list-style-type: none"> <li>➤ The concrete spalling at the</li> </ul>  |



|  |  |
|--|--|
| bottom right side of the right training wall with debonded rebar at the downstream face of the right training wall at the water line.  | downstream end of the left wall remains similar to that previously reported.     |
| ➤ Two diagonal cracks are located along the right training wall with efflorescence along the crack. The lower diagonal crack is more significant with delamination within two feet of the crack. | ➤ Cracking at the right training wall was consistent with that previously noted. |

**Spillway Cells**

For the purposes of inspection, individual cells were number consecutively from Cell No. 1 at the right end of the spillway to Cell No. 9 at the left end of the spillway adjacent to the fish ladder, consistent with the previous inspection. The following conventions were applied:

- The right and left sides of the cells are defined by the face of the rib adjacent to each cell facing into the cell (i.e., the left wall of Cell No. 1 refers to the right side of the rib between Cell No. 1 and Cell No. 2).
- The underside of the spillway slab was subdivided into 5 sections from downstream to upstream with:
  - Section 1 being the bottom of the downstream lip of the slab,
  - Section 2 being the upstream face of the downstream lip of the slab
  - Section 3 being the underside of the downstream slope of the spillway slab crest.
  - Section 4 being the underside of the spillway slab crest
  - Section 5 being the underside of the upstream slope of the spillway slab.

The following deficiencies were noted within the cells of the spillway following the preceding naming convention. Major deficiencies are listed in the table below. Please reference the Spillway Cell Inspection Figures for minor deficiencies and more specific detail about the dimensions and locations of the deficiencies listed below. The Spillway Cell Inspection Figure are included in Appendix A.

- In general, the concrete within the cells had scour along the apparent normal tailwater waterline.
- Map cracking was noted throughout the cell walls.
- Efflorescent staining was typical within all of the cells and typically indicated more severe deterioration.
- The spillway and ribs appeared to be constructed of concrete with aggregate up to 4 inches in diameter.
- The following was noted within the individual spillway cells:


**Cell #1**

| New Observations  |                       |                                  |
|---|-----------------------|----------------------------------|
| ➤ A 10-inch diameter spall approximately 10 inches deep was observed on the left half of the ceiling. |                       |                                  |
| Section   | Previous Observations | Comments from Current Inspection |



|            |  |   |
|------------|--|---|
| Right Wall | <ul style="list-style-type: none"> <li>➤ The joint at Face No. 3 appeared to be leaking as indicated by ice buildup on the wall. The joint was open approximately 0.5 inches.</li> <li>➤ Spalling was present along the wall up to 1.5-inches deep on the upstream half of the wall and on the bottom downstream half of the wall.</li> </ul>  | <ul style="list-style-type: none"> <li>➤ Low-flow leakage was observed along the top of the joint. Width of the joint remained near 0.5 inches</li> <li>➤ Concrete spalling continued to advance to 2-inches deep.</li> </ul>   |
| Left Wall  | <ul style="list-style-type: none"> <li>○ A 10-inch tall by 6-inch wide area of section loss was present through the wall between cell 1 and cell 2. Spalling was present within this area. Exposed aggregate around the hole was loose in areas and could be easily broken away with limited effort.</li> </ul>  | <ul style="list-style-type: none"> <li>➤ Section loss at the left wall continued to deteriorate. The section loss was measured to be 20 inches long by approximately 8 inches wide.</li> </ul>  |
| 1          | <ul style="list-style-type: none"> <li>➤ No major deficiencies noted. See Appendix A for more detail.</li> </ul>   | <ul style="list-style-type: none"> <li>➤ No Apparent Change</li> </ul>  |
| 2          | <ul style="list-style-type: none"> <li>➤ No major deficiencies noted. See Appendix A for more detail.</li> </ul>   | <ul style="list-style-type: none"> <li>➤ No Apparent Change</li> </ul>  |
| 3          | <ul style="list-style-type: none"> <li>➤ The downstream half of this face was repaired, with an 18-inch spall and delamination up to 1.5 inches deep present at the joint between the repair and original concrete.</li> <li>➤ An open joint with efflorescent staining was present at the joint between the left wall and the ceiling.</li> </ul>   | <ul style="list-style-type: none"> <li>➤ The spalling and delamination along the repaired section of the wall appeared to be consistent with that previously reported.</li> <li>➤ The joint between the left wall and the ceiling remained in similar condition to previous inspections.</li> </ul> |
| 4          | <ul style="list-style-type: none"> <li>➤ No major deficiencies noted. See Appendix A for more detail.</li> </ul>   | <ul style="list-style-type: none"> <li>➤ No apparent change</li> </ul>  |
| 5          | <ul style="list-style-type: none"> <li>➤ A spall approximately 4-feet long with exposed rebar was present at the left joint.</li> <li>➤ A repair was present along the right side, that was up to 0.25-inches thick. An approximate 0.5-inch separation was present between the existing and repaired concrete.</li> <li>➤ Orange staining was noted at the upstream most right corner.</li> <li>➤ Delamination with slight bulging was present along the center of the face.</li> </ul> | <ul style="list-style-type: none"> <li>➤ No apparent change. Hairline cracks with efflorescence staining were observed along the concrete repair.</li> </ul>  |
| Misc       | <ul style="list-style-type: none"> <li>➤ None</li> </ul>   | <ul style="list-style-type: none"> <li>➤ Concrete deterioration monitoring points were established at the left cell wall. Refer to the photo below and measurements to deterioration.</li> </ul>  |




|  |  |   |
|--|--|---|
|  |  |  <p>➤ The distance to the limits of deterioration on the left wall from the reference points are as follows:</p> <ul style="list-style-type: none"> <li>○ Top Reference: 2 inches</li> <li>○ Center between Top and Mid-References: 5.25 inches</li> <li>○ Middle Reference: 6 inches</li> <li>○ Center between Center and Bottom References: 3.5 inches</li> <li>○ Bottom Reference: 2.5 inches</li> </ul> |
|--|--|---|


**Cell #2**

| <b>New Observations:</b> |  |  |
|--------------------------|--|--|
| ➤ See Below.             |  |  |
| <b>Section</b>           | <b>Review of Previous Observations</b>   | <b>Comments from Current Inspection</b>  |
| Right Wall               | <ul style="list-style-type: none"> <li>➤ A spall approximately 3-inches wide, 0.5-inches deep with iron oxide staining was present along the full length of the upstream side of the wall.</li> <li>➤ A large spall with a 10-inch by 6-inch section of 100 percent section loss was present along the downstream end. The spall measures approximately 44-inches by 24-inches.</li> </ul> | <ul style="list-style-type: none"> <li>➤ Iron oxide staining was not observed during this inspection.</li> <li>➤ The concrete spalling has continued to deteriorate. The 10-inch by 6-inch hole was measured to be 20 inches long by 8 inches wide.</li> </ul> |
| Left Wall                | <ul style="list-style-type: none"> <li>○ A spall with a crack in the center was present along the downstream side of the wall and measured approximately 30-inches from the top to the bottom of the spall, 12-inches wide, and 5-inches deep.</li> </ul>  | <ul style="list-style-type: none"> <li>➤ The spall was measured to be 14 inches wide by 30 inches long.</li> </ul>   |
| 1                        | <ul style="list-style-type: none"> <li>➤ A spall was present at the downstream left end measuring 12-inches long, 4-inches wide, and up to 4-inches deep.</li> </ul>   | <ul style="list-style-type: none"> <li>➤ No apparent change.</li> </ul>  |



|      |  |   |
|------|--|---|
| 2    | <ul style="list-style-type: none"> <li>➤ No major deficiencies noted. See Appendix A for more detail.</li> </ul>   | <ul style="list-style-type: none"> <li>➤ No apparent change.</li> </ul>   |
| 3    | <ul style="list-style-type: none"> <li>➤ No major deficiencies noted. See Appendix A for more detail.</li> </ul>   | <ul style="list-style-type: none"> <li>➤ Map cracking with efflorescence observed.</li> </ul>   |
| 4    | <ul style="list-style-type: none"> <li>➤ No major deficiencies noted. See Appendix A for more detail.</li> </ul>   | <ul style="list-style-type: none"> <li>➤ No apparent change.</li> </ul>   |
| 5    | <ul style="list-style-type: none"> <li>➤ Delamination was present along the right side of the wall face. The repaired area appeared to be delaminating from the original concrete. Minor bulging within this area was also noted. The dimensions of the area of delamination vary and can be seen in more detail in Appendix A.</li> <li>➤ Iron oxide staining was noted at the right upstream most corner.</li> </ul> | <ul style="list-style-type: none"> <li>➤ Spalling was observed to be up to 2 inches deep near the bottom 5 feet of the wall.</li> <li>➤ No iron oxide staining was observed.</li> </ul>   |
| Misc | <ul style="list-style-type: none"> <li>➤ Ceiling face numbers 1, 2, and 3 were repaired or partially repaired. The repair on Ceiling face No. 3 typically measured 2 feet from the downstream joint with Ceiling Face No. 2. The repair was approximately 0.5-inches thick.</li> </ul>   | <ul style="list-style-type: none"> <li>➤ No apparent new repairs were made since the previous inspection.</li> <li>➤ Concrete deterioration monitoring points were established at the right cell wall. Refer to the photo below and measurements to deterioration.</li> </ul>  <ul style="list-style-type: none"> <li>➤ The distance to the limits of deterioration on the right wall from the reference points are as follows:             <ul style="list-style-type: none"> <li>○ Top Reference: 4 inches</li> <li>○ Center between Top and Mid-References: 6.75 inches</li> <li>○ Middle Reference: 8.5 inches</li> <li>○ Center between Center and Bottom References: 5 inches</li> <li>○ Bottom Reference: 5 inches</li> </ul> </li> </ul> |



|  |  |  |
|--|--|--|
|  |  |  <ul style="list-style-type: none"> <li>➤ The distance to the limits of deterioration on the left wall from the reference points are as follows:             <ul style="list-style-type: none"> <li>○ Top Reference: 4 inches</li> <li>○ Center between Top and Mid-References: 5.5 inches</li> <li>○ Middle Reference: 7 inches</li> <li>○ Center between Center and Bottom References: 2 inches</li> <li>○ Bottom Reference: 3.5 inches</li> </ul> </li> </ul> |
|--|--|--|

**Cell #3**

| <b>New Observations:</b>   |   |  |
|--|---|--|
| ➤ Spalling up to 12 inches wide and 1-inch deep was observed along the top 6 feet of the wall. |   |  |
| <b>Section</b>   | <b>Review of Previous Observations</b>  | <b>Comments from Current Inspection</b>  |
| Right Wall   | ➤ A spall was present at the downstream end measuring 25-inches long, 18-inches wide, and up to 2-inches deep.  | ➤ Spall measured to be 2.5 inches deep.  |
| Left Wall  | <ul style="list-style-type: none"> <li>○ A spall with debonded rebar was present at the downstream end measuring 25-inches long and 8-inches wide. A hand could be wrapped around the piece of rebar.</li> <li>○ An open crack/spall with delamination was present, approximately 3 to 4-inches wide. The crack within the spalled area is tight (near 1/8-inch wide).</li> </ul> | <ul style="list-style-type: none"> <li>➤ The 25-inch by 8-inch spall was measured to be up to 4 inches deep.</li> <li>➤ The open crack/spall appeared to be in similar condition.</li> </ul> |
| 1  | ➤ Areas of a past repair are apparent; the repair appears intact.   | ➤ No apparent change.  |
| 2  | ➤ Areas of a past repair are apparent; the  | ➤ No apparent change.  |



|      |   |  |
|------|---|--|
|      | repair appears intact.  |  |
| 3    | <ul style="list-style-type: none"> <li>➤ A partial repair was present along this face. The dimensions of the repair can be seen in more detail in Appendix A.</li> <li>➤ At the joint between the repair and the original concrete was a spall that measures up to 9-inches wide, 68-inches long, and up to 3.5-inches deep.</li> </ul> | ➤ The spall at end of repair was measured to be up to 4 inches deep. |
| 4    | ➤ No major deficiencies noted. See Appendix A for more detail.  | ➤ No apparent change.  |
| 5    | ➤ No major deficiencies noted. See Appendix A for more detail.  | ➤ See new observations.  |
| Misc | ➤ None.   | ➤ N/A  |

**Cell #4**

| New Observations:   |  |  |
|---|--|--|
| <ul style="list-style-type: none"> <li>➤ Moisture was observed along the top of the right wall near the joint at ceiling face No. 3.</li> <li>➤ Map cracking was typical of the left and right cell walls.</li> </ul> |  |  |
| Section   | Review of Previous Observations  | Comments from Current Inspection   |
| Right Wall  | <ul style="list-style-type: none"> <li>➤ A spall with a 4-inch long, 0.040-inch wide crack was present at the downstream end. The spall measured 30-inches tall, 22-inches wide and up to 4-inches deep. A 5-inch deep cored hole was present within the approximate center of the spall.</li> <li>➤ A crack with iron oxide staining was present along the upstream edge. The crack was up to 6-inches wide and 2-inches deep. Seepage appeared to be evident based upon ice along the wall below the crack.</li> </ul> | <ul style="list-style-type: none"> <li>➤ The spall at the downstream end of the wall appeared to be in similar condition.</li> <li>➤ Approximately ½-inch of displacement was observed on either side of the crack at the upstream bottom corner of the wall.</li> </ul> |
| Left Wall   | <ul style="list-style-type: none"> <li>○ A spall with debonded rebar was present along the downstream end measuring 18-inches long, 18-inches wide, and up to 4-inches deep.</li> </ul>  | ➤ No apparent change.  |
| 1   | ➤ Debonded rebar and spalling was present on the right end, measured to be approximately 6-inches wide by 16-inches long.  | ➤ No apparent change.  |
| 2   | ➤ Areas of a past repair are apparent; the repair appears intact.  | ➤ No apparent change.  |
| 3   | ➤ Areas of past repairs are apparent; the repairs appear to be intact.   | ➤ 1-inch deep spall at exposed rebar was observed near the downstream end of the face.   |
| 4   | ➤ No specific observations.  | ➤ No apparent change.  |
| 5   | ➤ Three spalls were present along the upstream toe of this wall. Iron oxide staining was present on either side of this wall within the spalls. A section of debonded rebar was also present.  | ➤ The center spall was measured to be up to 2.5 inches deep.   |



|      |         |       |
|------|---------|-------|
| Misc | ➤ None. | ➤ N/A |
|------|---------|-------|

**Cell #5**

| <b>New Observations:</b>  |   |  |
|---|---|--|
| ➤ Delaminated concrete was observed along the upstream side of the right cell wall. |   |  |
| <b>Section</b>  | <b>Review of Previous Observations</b>  | <b>Comments from Current Inspection</b>  |
| Right Wall  | ➤ A spall with debonded rebar was present at the downstream end measuring 3-feet long, 1-foot wide and approximately 3.5-inches deep. | ➤ No Apparent Change   |
| Left Wall   | ○ No significant areas of deterioration were noted.   | ➤ Exposed aggregate was observed at the downstream end of the cell wall.                                 |
| 1   | ➤ Areas of past repairs are apparent; the repairs appear to be intact.  | ➤ No apparent change.  |
| 2   | ➤ Areas of past repairs are apparent; the repairs appear to be intact.  | ➤ 3.5-inch wide by 8-inch long spall observed at the bottom left portion of the repair.                  |
| 3   | ➤ No major deficiencies noted. See Appendix A for more detail.  | ➤ No apparent change.  |
| 4   | ➤ No major deficiencies noted. See Appendix A for more detail.  | ➤ No apparent change.  |
| 5   | ➤ No major deficiencies noted. See Appendix A for more detail.  | ➤ A 10-inch diameter spall approximately ½ inch deep was observed at the right side of the ceiling face. |
| Misc  | ➤ None.   | ➤ N/A  |

**Cell #6**

| <b>New Observations:</b>   |  |   |
|--|--|---|
| ➤ A 6-inch wide by 16-inch long spall, approximately 1.5 inches deep was observed near the downstream end of the left wall adjacent to ceiling face no. 2. |  |   |
| <b>Section</b>   | <b>Review of Previous Observations</b>   | <b>Comments from Current Inspection</b>             |
| Right Wall   | ➤ No significant areas of deterioration were noted.  | ➤ No apparent change                                |
| Left Wall  | ○ A spall with delamination and efflorescent staining was present on the upstream side measuring 18 inches long by 6 inches wide.    | ➤ Moisture was observed at the center of the spall. |
| 1  | ➤ Spall with debonded rebar was present on the left portion of the ceiling face and measured 14-inches long and up to 2-inches deep. | ➤ No apparent change.                               |
| 2  | ➤ A 2 to 6-inch wide repair was present along the downstream edge of the face.   | ➤ No apparent change.                               |
| 3  | ➤ An 8-inch diameter previously repaired spalled area was present on the right side of   | ➤ No apparent change.                               |





|      |  |  |
|------|--|--|
|      | the ceiling face.  |  |
| 4    | ➤ No specific observations.  | ➤ A 24-inch wide section at the left side of the ceiling face was delaminated. |
| 5    | ➤ Three spalls with delamination were present along the left edge of the wall. | ➤ No apparent change.  |
| Misc | ➤ None.  | ➤ N/A  |

**Cell #7**

| <b>New Observations:</b>   |   |  |
|--|---|--|
| ➤ Approximately 1.5 inches of scour was observed along the left cell wall approximately 5 inches above the base of the wall. |   |  |
| <b>Section</b>   | <b>Review of Previous Observations</b>  | <b>Comments from Current Inspection</b>  |
| Right Wall   | <ul style="list-style-type: none"> <li>➤ A spall with exposed aggregate was present on the downstream end measuring 14-inches wide and up to 3-inches deep.</li> <li>➤ An open crack with exposed aggregate was present along the upstream perimeter of the wall approximately 1 to 6-inches from the ceiling. The spalling around the crack was approximately 6-inches wide and up to 2.5-inches deep. Seepage appeared to be evident based on ice on the wall below the crack.</li> <li>➤ The concrete above the crack was sounded for deterioration and appeared to be delaminated.</li> </ul> | <ul style="list-style-type: none"> <li>➤ The 14-inch wide spall appeared to be in similar condition.</li> <li>➤ The open crack along the upstream perimeter of the wall was measured to be up to 8 inches wide. No moisture/leakage was observed at the time of the inspection.</li> <li>➤ Concrete above the crack appeared in similar condition to the previous inspection.</li> </ul> |
| Left Wall  | <ul style="list-style-type: none"> <li>○ A spall up to 1.5-inches deep was present on the downstream end of the wall.</li> </ul>  | ➤ No apparent change.  |
| 1  | ➤ Areas of past repairs are apparent; the repairs appear to be intact.  | ➤ No apparent change.  |
| 2  | ➤ Areas of past repairs are apparent; the repairs appear to be intact.  | ➤ No apparent change.  |
| 3  | ➤ The face was sounded and appeared to be significantly delaminated. Significant efflorescent staining buildup was present.   | ➤ Spalling up to 24 inches long by 36 inches wide and approximately 1.5 inches deep was observed at the upstream end of the ceiling face.  |
| 4  | ➤ No major deficiencies noted. See Appendix A for more detail.  | ➤ No apparent change.  |
| 5  | ➤ No major deficiencies noted. See Appendix A for more detail.  | ➤ No apparent change.  |
| Misc   | ➤ None.   | ➤ N/A  |

**Cell #8**

| <b>New Observations:</b>   |
|--|
| <ul style="list-style-type: none"> <li>➤ Scour up to 9 inches wide and 2.5 inches deep was observed at the downstream end of the right cell wall.</li> <li>➤ Scour was approximately 2 inches deep at the downstream end of the left cell wall.</li> </ul> |



| Section    | Review of Previous Observations  | Comments from Current Inspection   |
|------------|--|--|
| Right Wall | ➤ A total of eight repairs appeared to be present on the wall; five of the apparent repairs were not visible due to timber falsework over the repairs. | ➤ No apparent change.  |
| Left Wall  | ○ Five apparent repairs were present on the wall, the repairs were not visible due to timber falsework over the repairs.                               | ➤ No apparent change.  |
| 1          | ➤ Areas of past repairs are apparent; the repairs appear to be intact.   | ➤ No apparent change.  |
| 2          | ➤ Areas of past repairs are apparent; the repairs appear to be intact.   | ➤ No apparent change.  |
| 3          | ➤ A 3-inch diameter, 0.5-inch deep spall with exposed rebar was present on the upstream edge of the ceiling face.                                      | ➤ No apparent change.  |
| 4          | ➤ No specific observations.  | ➤ No apparent change.  |
| 5          | ➤ A spall with exposed rebar was present on the downstream end of the face that measured 4-feet long and up to 8-inches wide.                          | ➤ No apparent change. Spalling was measured to be approximately 1-inch deep. |
| Misc       | ➤ None.  | ➤ N/A  |

**Cell #9**

| Current Observations: |  |   |
|-----------------------|--|---|
| ➤                     |  |   |
| Section               | Review of Previous Observations  | Comments from Current Inspection                                  |
| Right Wall            | ➤ No major deficiencies noted. See Appendix A for more detail.             | ➤ Scour along the right cell wall was measured to be 1-inch deep. |
| Left Wall             | ○ No major deficiencies noted. See Appendix A for more detail.             | ➤ No apparent change.   |
| 1                     | ➤ No major deficiencies noted. See Appendix A for more detail.             | ➤ No apparent change.   |
| 2                     | ➤ No major deficiencies noted. See Appendix A for more detail.             | ➤ No apparent change.   |
| 3                     | ➤ No major deficiencies noted. See Appendix A for more detail.             | ➤ No apparent change.   |
| 4                     | ➤ No major deficiencies noted. See Appendix A for more detail.             | ➤ No apparent change.   |
| 5                     | ➤ No major deficiencies noted. See Appendix A for more detail.             | ➤ No apparent change.   |
| Misc                  | ➤ No major deficiencies or specific observations were noted in Cell No. 9. | ➤ No apparent change.   |



The following was noted on the downstream side of the ribs:

| <b>New Observations:</b>  |   |
|---|---|
| ➤ The spalling at the top of the rib between cell 7 and cell 6 was approximately 4 inches deep.                         |   |
| <b>Review of Previous Observations</b>  | <b>Comments from Current Inspection</b> |
| ➤ In general, spalling was present along either side of each rib.   | ➤ No apparent change                    |
| ○ The rib between Cell Nos. 3 and 4 was spalled with debonded rebar. A hand could be wrapped around the debonded rebar. | ➤ No apparent change                    |
| ➤ The rib between cells 4 and 5 had a 3-foot tall spall with debonded rebar.  | ➤ No apparent change                    |

### 2.1.4 Gated Outlet Structure

The following was noted at the outlet structure:

#### Upstream Face

| <b>Current Observations:</b>   |   |
|--|---|
| ➤ The right and left gate inverts appear to be scoured and deteriorating.  |   |
| ➤ Scour is present throughout the upstream face at the waterline.  |   |
| ➤ Hairline cracking is present throughout the upstream face of the gated outlet structure.                                     |   |
| <b>Review of Previous Observations</b>   | <b>Comments from Current Inspection</b>   |
| ➤ A spalled section, approximately 6 to 8-inches wide, was present on the right side of left gate invert at the waterline.     | ➤ No apparent change.   |
| ○ The right gate invert was submerged at the time of the inspection.   | ➤ No apparent change. The right gate invert was submerged at the time of inspection.                    |
| ➤ Moss/ice/snow cover was present on the upstream face of the concrete at the low level outlet structure, limiting inspection. | ➤ Ice and snow cover was not present during the time of inspection.<br>➤ Minor moss growth was present. |

#### Crest

| <b>Current Observations:</b>   |   |
|--|---|
| ➤ Hairline cracking is present along the crest of the gated outlet structure.  |   |
| ➤ Cracking and deterioration is present on the downstream face of the crest.   |   |
| ➤ The areas of the crest surrounding the gate structures appear to be deteriorating with minor spalling.               |   |
| ➤ Minor leaf debris and moss growth are present throughout the crest.  |   |
| <b>Review of Previous Observations</b>   | <b>Comments from Current Inspection</b>                             |
| ➤ Moss/ice/snow cover was present on the crest of the concrete at the low level outlet structure, limiting inspection. | ➤ Ice and snow cover was not present during the time of inspection. |



**Downstream Face**

| <b>Current Observations:</b>  |  |
|---|--|
| <ul style="list-style-type: none"> <li>➤ Concrete spalling with section loss is present along the downstream end of the wall left of the left outlet gate.</li> <li>➤ Brush growth is present on top of the concrete cap surrounding the outlet pipe.</li> <li>➤ Stick and leaf debris are present in the discharge area.</li> <li>➤ Displaced stones are present immediately downstream of the downstream wall.</li> <li>➤ Stick debris and unwanted vegetation are present in the area immediately downstream of the stone wall.</li> </ul> |  |
| <b>Review of Previous Observations</b>  | <b>Comments from Current Inspection</b>  |
| ➤ Map cracking was present throughout the gate structure headwall.  | ➤ No apparent change.  |
| ○ Concrete spalling with exposed rebar was present to the left of the left gate outlet. The spall measured approximately 2-feet wide by 2-feet tall and up to 3.5-inches deep.  | ➤ No apparent change.  |
| <ul style="list-style-type: none"> <li>➤ The concrete along the bottom portion of the wall (approximately 5 feet from mudline at the wall) was significantly deteriorated with efflorescence/iron oxide staining.                             <ul style="list-style-type: none"> <li>○ Significant delamination with exposed rebar was present on either side of the old pipe from the mill structure. The scour and spall were up to 4-inches deep</li> </ul> </li> </ul>  | ➤ Significant deterioration and efflorescent staining was present along the concrete bottom portion of the wall. |
| ➤ Seepage, approximately 0.5 gpm, was present through the downstream face of the gate structure at the concrete to the left of the right outlet.  | ➤ No apparent change.  |
| ➤ Seepage, approximately 1 to 2 gpm, was present through the downstream face of the gate structure between the two outlets approximately 2 feet above the top of the left gate opening.   | ➤ Low-flow leakage was observed between the two outlets and 2 feet above the right outlet.                       |
| ➤ Signs of potential seepage appeared to be present due to the presence of ice along the downstream face of the concrete at the gate headwall.  | ➤ Areas of moisture, low-flow leakage observed throughout the downstream face of the wall.                       |
| ➤ The right gate outlet pipe was fully corroded.  | ➤ No apparent change.  |
| ➤ Section loss and scour was present at the right end of the concrete cap surrounding the outlet pipe.  | ➤ No apparent change.  |
| ➤ The downstream masonry wall immediately right of the right outlet appears to bulge in the downstream direction approximately 6-inches between the gate section and the old mill foundation. Seepage was present at the base of this section of wall, flowing at approximately ten gallons per minute.   | ➤ No apparent change. Seepage was limited to low-flow and may be mistaken of tidal waters.                       |
| ➤ No chinking stones or mortar were present within the downstream wall or the walls at the abutment.  | ➤ No apparent change.  |
| ➤ A crack/spall was present on the to the left of the left gate outlet extending from the right side of the right training wall to the gate outlet. The crack was   | ➤ No apparent change.  |



|  |  |
|--|--|
| approximately 3-inches wide and up to 2-inches deep. |  |
|--|--|

**Gates/Conduits**

|  |   |
|--|---|
| <b>Current Observations:</b>   |   |
| ➤ The interior of the gate structures appears to be scoured and deteriorated.  |   |
| <b>Review of Previous Observations</b>   | <b>Comments from Current Inspection</b>                   |
| ➤ The left gate was operable, but the gate was reportedly limited to an opening of 8-inches.                                   | ➤ No apparent change.                                     |
| ○ Leakage through the left gate is approximately 1 to 3 cfs.   | ➤ No apparent change, leakage continued through the gate. |
| ➤ The left gate was operated during the inspection to lower the levels within the impoundment.                                 | ➤ No apparent change.                                     |
| ➤ The right gate was reportedly inoperable. The gate was historically used for the mill that was once downstream of this gate. | ➤ No apparent change.                                     |

**2.1.5 Fish Ladder**

The following was noted at the fish ladder:

|   |   |
|---|---|
| <b>Current Observations:</b>  |   |
| <ul style="list-style-type: none"> <li>➤ Minor scour was present along the waterline of the interior of the fish ladder.</li> <li>➤ Minor leaf debris was present at the approach to the stop logs at the upstream side of the fish ladder.</li> <li>➤ Minor vine growth was present along the downstream side of the fish ladder metal grating.</li> <li>➤ The upstream left corner of the fish ladder appeared to be overgrown with brush and vegetation.</li> <li>➤ Concrete scour with deterioration was present on the right side of the downstream end of the fish ladder.</li> </ul> |   |
| <b>Review of Previous Observations</b>  | <b>Comments from Current Inspection</b> |
| ➤ The fish ladder structure consisted of timber baffles.  | ➤ No apparent change.                   |
| ○ The stop logs at the upstream side of the fish ladder exit pool were leaking approximately 5 gpm.   | ➤ No apparent change.                   |
| ➤ Scour was present along the water line of the fish ladder pool structure.   | ➤ No apparent change.                   |
| ➤ The grating over the fish ladder structure appeared to be in good condition.  | ➤ No apparent change.                   |
| ➤ The footing for the training wall between the fish ladder and Cell No. 9 was undermined at the base of the wall. The void was probed up to 3 feet under the training wall. The undermined area was approximately 2-feet long and 1-foot in height.  | ➤ No apparent change.                   |
| ➤ An open construction joint was present at the 180-degree turn in the fish ladder and was approximately 1-inch wide.   | ➤ No apparent change.                   |
| ➤ A repair was present along the right side of the downstream training wall. The repair area showed indications of delamination.  | ➤ No apparent change.                   |



|   |                              |
|---|------------------------------|
| <p>➤ An open joint with vegetation growing was present at the concrete between the primary spillway and fish ladder structure. This area was previously reported to be leaking, but flow over the spillway limited the view of any leakage.</p> | <p>➤ No apparent change.</p> |
|---|------------------------------|

**2.1.6 Downstream Area**

The water immediately downstream of the Mill Pond Dam is tidal and is considered brackish. Immediately downstream of the spillway is a 10 to 15-foot wide plunge pool lined with boulders and bedrock. Water flows from the plunge pool and passes under Newmarket Road in a bedrock and boulder lined channel, approximately 100 feet downstream of the spillway. The bridge at Newmarket Road appeared to be founded on bedrock and in good condition with no signs of scour. Flows through the Newmarket Road Bridge then pass under a pedestrian bridge approximately 200 feet downstream before entering Little Bay and eventually the Piscataqua River.

**2.1.7 Reservoir Area**

The dam is located at the eastern end of the impoundment. Mill Pond extends approximately 1,000 feet upstream of the dam; however, the dam also impounds water upstream along the Oyster River and Hamel Brook with backwater influences from the dam extending 2,800 feet upstream of the pond along the Oyster River and approximately 1,900 feet upstream of the Oyster River along the Hamel Brook.

The perimeter of the impoundment is generally un-developed along the immediate shoreline with few residential properties around the impoundment. Mill Pond Road borders the impoundment to the north. Slopes are generally flat surrounding the impoundment area.

**2.2 Caretaker Interview**

Ms. April Talon was present during the inspection. Information provided by Ms. Talon has been incorporated into this report.

**2.3 Operation and Maintenance Procedures**

There was no formal operations and maintenance manual for the dam available at the time of the inspection.

**2.3.1 Operational Procedures**

Operable components include the two gates at the low-level outlet. The right most-gate is inoperable and was previously used as hydropower when the mill was operational. The left-most gate is operable though the range of operability is limited to approximately 8 inches. The fish ladder structure does not appear to have significant capacity to be considered as an operational outlet to the dam; stoplogs may be adjusted as necessary to support fish migration.

**2.3.2 Maintenance of Dam and Operating Facilities**

Maintenance activities at the dam include cutting of vegetation along the left abutment and clearing the spillway and discharge area of debris. The caretaker also routinely completes informal



inspections and responses to public comments to check the condition of the dam. In general, the caretaker was knowledgeable of current conditions at the dam.

As part of this inspection, monitoring points were installed along the concrete deterioration of the left cell wall of Cells 1 and 2, and the right cell wall of Cell 2. Measurements of these monitoring points are provided in Appendix A.



### 3.0 ASSESSMENTS

#### 3.1 Assessments

In general, the overall condition of the Mill Pond Dam is **Poor** with the following deficiencies identified:

**TABLE 3.1: Deficiency Summary**

| <i>Deficiency Number</i> | <i>Description</i>   |
|--------------------------|--|
| 1                        | Severe deterioration of the spillway cells and ribs including: <ul style="list-style-type: none"> <li>• Cracks and spalls with evidence of leakage;</li> <li>• Section loss of the rib between Cell Nos. 1 and 2;</li> <li>• Delamination of the repaired concrete from the original concrete;</li> <li>• Debonded rebar within multiple cells;</li> </ul> |
| 2                        | Seepage at the downstream corner of the right stone masonry abutment wall; Low flow seepage observed.  |
| 3                        | Leakage through the downstream face of the outlet structure and through the timber gate.   |
| 4                        | Inoperable right gate outlet;  |
| 5                        | Concrete deterioration at the gate outlet structure including delamination, cracking, and spalling;  |
| 6                        | Insufficient capacity to pass the SDF;   |

In general, the conditions observed during this inspection have continued to deteriorate since the previous inspections.

The following table provides a summary of previous recommendations and their status at the time of the inspection:

| <i>Previously Identified Deficiency</i>  | <i>Resolution or Current Condition</i>   |
|--|--|
| Concrete deterioration and spalling on the downstream face of the outlet works, ribs, interior of the spillway cells | <i>Deterioration has continued to progress. The area of section loss between Cell Nos. 1 and 2 has increased in size since the 2019 inspection by Pare. Deterioration continues. As part of this inspection, concrete deterioration references were established.</i> |
| Minor seepage at the downstream corner of the right masonry abutment wall  | <i>Seepage not observed during the time of the inspection, but wet areas were observed.</i>  |
| Insufficient ability to pass the design storm with one foot of freeboard at the dam                                  | <i>Same deficiency; No action taken.</i>   |
| Deterioration of the mid-1970's concrete repair work   | <i>Deterioration has continued to progress</i>   |
| EAP needs updating and testing   | <i>No apparent change</i>  |
| Update O&M manual  | <i>No apparent change</i>  |
| Leakage at the outlet structure  | <i>Leakage through the timber gate remains</i>   |
| Inoperable right gate outlet   | <i>No action taken; gate remains inoperable.</i>   |
| Seepage through the downstream face of the gate structure  | <i>Leakage remains left and right of the left outlet.</i>  |





### 3.2 Current Hazard Potential Classification

The Mill Pond Dam is currently classified as a **Low** hazard potential dam due to the impacts dam failure may have on the adjacent and downstream properties and because the height exceeds 6 feet, and the storage capacity exceeds 50 acre-feet.

According to an NHDES letter dated April 17, 2020 Mill Pond Dam is classified as low not only because of the “6/50” case, but also the potential for damage to be done to the property to the right of the dam if failure or overtopping occurs. This letter was in response to a detailed H&H analysis and memorandum by Weston & Sampson, dated March 4, 2020.

### 3.3 Hydraulic/Hydrologic Data

Mill Pond Dam is a **Low** hazard structure and in accordance with current state dam safety regulations, the spillway design flood (SDF) for the site is the 50-year storm event. A detailed hydraulic and hydrologic analysis was completed for the dam and was included within the “Feasibility Study – NHDES Dam #071.03 Oyster River Dam at Mill Pond”, dated November 2020, by VHB. According to the H&H analysis completed as part of that study, the dam will be overtopped on the right abutment by 1.74 feet and cannot pass the 50-year storm with one-foot of free board as required by current dam safety regulations. The following table summarizes the results of the H&H analysis.

| Storm Event | Inflow (cfs) | Peak El. (ft) | Spillway Discharge (cfs) |               |
|-------------|--------------|---------------|--------------------------|---------------|
|             |              |               | With 1 ft freeboard      | At top of Dam |
| 50-year     | 3,352        | 14.62         | 352                      | 1,015         |
| 100-year    | 3,877        | 15.04         |                          |               |

### 3.4 Structural and Seepage Stability

A structural stability analysis was performed by Stephens Associates as part of the 2009 Inspection Report. No records of the original design computations were available for review at the time of the preparation of this report.

#### 3.4.1 Structural Stability of Dam

Stephens Associates completed a structural stability analysis as part of the 2009 Inspection report. The following table summarizes the results of that analysis:

| Case                                 | FS for Sliding | Eccentricity (ft) | Maximum Bearing Pressure (psf) |
|--------------------------------------|----------------|-------------------|--------------------------------|
| Spillway – Normal Flow               | 2.0            | 0.33              | 7,300                          |
| Spillway – Flood                     | 2.2            | 1.14              | 9,500                          |
| Right Abutment – Normal Flow         | 1.7            | 1.3               | 1,030                          |
| Right Abutment – Flood               | 1.4            | 2.3               | 840                            |
| Right Abutment – Ice and Normal Flow | <1             | 6.4               | 1,040                          |

According to NHDES Env-Wr 303.12(c)(2), the stability analysis shall follow the methods outlined in “Engineering Guidelines for Evaluation of Hydropower Projects” published by the Federal



Energy Regulatory Commission (FERC) Chapter 3 dated 2002 and Chapter 4 dated 1991. The guidelines mentioned state that a minimum factor of safety of 1.5 must be met for the worst static load case.

The results show that the spillway is stable against flood conditions and the spillway and right abutment (gated outlet structure) are stable against normal flow conditions. The right abutment does not meet the factor of safety of 1.5 for the flood and normal pool with ice conditions.

The downstream masonry wall and right abutment masonry wall are generally vertical. The right abutment masonry wall was reconstructed in 2009 after a storm event overtopped the right abutment and washed out the previous masonry wall. The right abutment masonry wall is slightly bulging, but appears to be stable. The spillway continues to deteriorate with section loss through the rib between cell 1 and 2. The section loss was not apparent during the inspection in 2009.

### **3.4.2 Seepage Stability**


No formal seepage analyses have been completed for this structure. Seepage and orange staining were observed at the bottom of the masonry walls along the right abutment and through the downstream side of the outlet structure. It is unknown whether the seepage through the right abutment masonry wall is due to potentially high water table right of the dam or from the dam impoundment. Two areas of seepage were noted through the concrete of the outlet structure.

Active seepage was noted within Cell No. 1 on the connecting low level outlet wall. No seepage was observed within Cell No. 2 on the right wall but was previously identified within the inspection report by NHDES dated September 18, 2017.



**FIGURES**  
*Mill Pond Dam*  
*Durham, NH*






**MILL POND DAM**  
 DAM #071.03  
 DURHAM, NEW HAMPSHIRE

**LOCUS PLAN**

OWNER - TOWN OF DURHAM

OCTOBER 2021

FIGURE 1



SCALE: 1"=150'

MILL POND DAM  
 43.1305° N  
 70.9194° W  
 DOVER WEST, NH USGS QUAD

USGS ORTHOPHOTO FROM OFFICE OF NEW HAMPSHIRE'S  
 STATEWIDE GIS CLEARINGHOUSE (NH GRANIT)


1"=1500'  
 0" ————— 1"



MILL POND DAM  
 DAM #071.03  
 DURHAM, NEW HAMPSHIRE  
 OWNER - TOWN OF DURHAM

AERIAL PLAN  
 OCTOBER 2021      FIGURE 2

X:\JOBS\19 Jobs\19169.00 VHB-OysterRiver-Mill Pond Dam Feasibility-MA\REPORTS\Dam Inspection 2021\Drawings\FIG 3 Site Sketch.dwg



**SITE SKETCH**  
SCALE: 1"=20'±

**NOTES AND LEGEND**

1. PLAN DEVELOPED FROM A SURVEY PLAN PREPARED BY VHB, INC. DATED DECEMBER 18, 2019 AND NOTES TAKEN DURING THE INSPECTION. INFORMATION IS PROVIDED FOR REFERENCE PURPOSES ONLY.
2. ELEVATIONS REFERENCE THE NAVD 88 VERTICAL DATUM.
3. SPOT ELEVATION AS DETERMINED BY VHB, INC. REFERENCING EITHER BM 1, BM 2, OR BM 3.
- 3.0\* SPOT ELEVATION AS DETERMINED BY A RELATIVE ELEVATION SURVEY COMPLETED BY PARE CORPORATION DURING THE INSPECTION
- Ⓢ DENOTES APPROXIMATE LOCATION AND DIRECTION OF PHOTOGRAPH.

| REVISIONS: |  |
|------------|--|
|            |  |
|            |  |
|            |  |
|            |  |

|              |              |
|--------------|--------------|
| PROJECT NO.: | 19169.00     |
| DATE:        | OCTOBER 2021 |
| SCALE:       | AS NOTED     |
| DESIGNED BY: | BMD          |
| CHECKED BY:  | BMD          |
| DRAWN BY:    | LMC          |
| APPROVED BY: | ARO          |

**APPENDIX A**  
**Spillway Cell Inspection Figures**  
*Mill Pond Dam*  
*Durham, NH*



REVISIONS:


| NO. | DESCRIPTION |
|-----|-------------|
|     |             |
|     |             |
|     |             |
|     |             |

PROJECT NO.: 19169.00  
 DATE: OCTOBER 2021  
 SCALE: NTS  
 DESIGNED BY: BMD  
 CHECKED BY: ARO  
 DRAWN BY: BMD  
 APPROVED BY: ARO


CELL NO. 1

SHEET NO.:


1




**RIGHT CELL WALL**  
 NOT TO SCALE




**LEFT CELL WALL**  
 NOT TO SCALE



**DETERIORATION MONITORING**  
 NOT TO SCALE



**UPSTREAM WALL AND CEILING OF CELL**  
 NOT TO SCALE



**SPILLWAY DOWNSTREAM FACE AND BUTTRESSES**  
 NOT TO SCALE

NOT FOR CONSTRUCTION



REVISIONS:



| NO. | DESCRIPTION |
|-----|-------------|
|     |             |
|     |             |
|     |             |
|     |             |

PROJECT NO.: 19169.00  
 DATE: OCTOBER 2021  
 SCALE: NTS  
 DESIGNED BY: BMD  
 CHECKED BY: ARO  
 DRAWN BY: BMD  
 APPROVED BY: ARO



CELL NO. 2

SHEET NO.:

2




CONCRETE MONITORING LEFT WALL  
 NOT TO SCALE




LEFT CELL WALL  
 NOT TO SCALE

CONCRETE MONITORING RIGHT WALL  
 NOT TO SCALE



UPSTREAM WALL AND CEILING OF CELL  
 NOT TO SCALE



SPILLWAY DOWNSTREAM FACE AND BUTTRESSES  
 NOT TO SCALE



**PARE CORPORATION**  
 ENGINEERS - SCIENTISTS - PLANNERS  
 10 LINCOLN ROAD, SUITE 210  
 FOXBORO, MA 02035  
 508-543-1755

SCALE ADJUSTMENT  
 GUIDE  
 0" 1"  
 BAR IS ONE INCH ON  
 ORIGINAL DRAWING.


**MILL POND DAM - 2021 DAM INSPECTION**  
 DURHAM, NH  
 OWNER: TOWN OF DURHAM

| REVISIONS: |  |
|------------|--|
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |


PROJECT NO.: 19169.00  
 DATE: OCTOBER 2021  
 SCALE: NTS  
 DESIGNED BY: BMD  
 CHECKED BY: ARO  
 DRAWN BY: BMD  
 APPROVED BY: ARO

CELL NO. 3


SHEET NO.: 3




**RIGHT CELL WALL**  
 NOT TO SCALE



**LEFT CELL WALL**  
 NOT TO SCALE



**UPSTREAM WALL AND CEILING OF CELL**  
 NOT TO SCALE



**SPILLWAY DOWNSTREAM FACE AND BUTTRESSES**  
 NOT TO SCALE

NOT FOR CONSTRUCTION

F:\086\19 Jobs\19169.00 WB-OysterRiver-Mill Pond Dam Feasibility-MA\REPORTS\Dam Inspection 2021\Drawings\Crack Inspection DWG\CELL 3.dwg



**PARE CORPORATION**  
 ENGINEERS - SCIENTISTS - PLANNERS  
 10 LINCOLN ROAD, SUITE 210  
 FOXBORO, MA 02035  
 508-543-1755

SCALE ADJUSTMENT GUIDE  
 0" 1"  
 BAR IS ONE INCH ON ORIGINAL DRAWING.


**MILL POND DAM - 2021 DAM INSPECTION**  
 DURHAM, NH  
 OWNER: TOWN OF DURHAM

| REVISIONS: |  |
|------------|--|
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |


PROJECT NO.: 19169.00  
 DATE: OCTOBER 2021  
 SCALE: NTS  
 DESIGNED BY: BMD  
 CHECKED BY: ARO  
 DRAWN BY: BMD  
 APPROVED BY: ARO

CELL NO. 4


SHEET NO.: 4




**RIGHT CELL WALL**  
 NOT TO SCALE



**LEFT CELL WALL**  
 NOT TO SCALE



**UPSTREAM WALL AND CEILING OF CELL**  
 NOT TO SCALE



**SPILLWAY DOWNSTREAM FACE AND BUTTRESSES**  
 NOT TO SCALE

NOT FOR CONSTRUCTION

F:\086\19 Jobs\19169.00 WB-OysterRiver-Mill Pond Dam Feasibility-MA\REPORTS\Dam Inspection 2021\Drawings\Crack Inspection DWG\CELL 4.dwg



**PARE CORPORATION**  
 ENGINEERS - SCIENTISTS - PLANNERS  
 10 LINCOLN ROAD, SUITE 210  
 FOXBORO, MA 02035  
 508-543-1755

SCALE ADJUSTMENT GUIDE  
 0" 1"  
 BAR IS ONE INCH ON ORIGINAL DRAWING.

**MILL POND DAM - 2021 DAM INSPECTION**  
 DURHAM, NH  
 OWNER: TOWN OF DURHAM


| REVISIONS: |  |
|------------|--|
|            |  |
|            |  |
|            |  |
|            |  |
|            |  |

PROJECT NO.: 19169.00  
 DATE: OCTOBER 2021  
 SCALE: NTS  
 DESIGNED BY: BMD  
 CHECKED BY: ARO  
 DRAWN BY: BMD  
 APPROVED BY: ARO


CELL NO. 5

SHEET NO.:


**5**




**RIGHT CELL WALL**  
 NOT TO SCALE



**LEFT CELL WALL**  
 NOT TO SCALE




**UPSTREAM WALL AND CEILING OF CELL**  
 NOT TO SCALE




**SPILLWAY DOWNSTREAM FACE AND BUTTRESSES**  
 NOT TO SCALE

**NOT FOR CONSTRUCTION**


F:\086\19 Jobs\19169.00 WB-OysterRiver-Mill Pond Dam Feasibility-MA\REPORTS\Dam Inspection 2021\Drawings\Crack Inspection Dwg\CELL 5.dwg




**RIGHT CELL WALL**  
 NOT TO SCALE



**LEFT CELL WALL**  
 NOT TO SCALE



**UPSTREAM WALL AND CEILING OF CELL**  
 NOT TO SCALE



**SPILLWAY DOWNSTREAM FACE AND BUTTRESSES**  
 NOT TO SCALE

REVISIONS:

| NO. | DATE | DESCRIPTION |
|-----|------|-------------|
|     |      |             |
|     |      |             |
|     |      |             |
|     |      |             |

PROJECT NO.: 19169.00  
 DATE: OCTOBER 2021  
 SCALE: NTS  
 DESIGNED BY: BMD  
 CHECKED BY: ARO  
 DRAWN BY: BMD  
 APPROVED BY: ARO

CELL NO. 6

SHEET NO.:

6

NOT FOR CONSTRUCTION



**PARE CORPORATION**  
 ENGINEERS - SCIENTISTS - PLANNERS  
 10 LINCOLN ROAD, SUITE 210  
 FOXBORO, MA 02035  
 508-543-1755

SCALE ADJUSTMENT  
 GUIDE  
 0" 1"  
 BAR IS ONE INCH ON  
 ORIGINAL DRAWING.

**MILL POND DAM - 2021 DAM INSPECTION**  
 DURHAM, NH  
 OWNER: TOWN OF DURHAM


REVISIONS:

|  |  |
|--|--|
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |


PROJECT NO.: 19169.00  
 DATE: OCTOBER 2021  
 SCALE: NTS  
 DESIGNED BY: BMD  
 CHECKED BY: ARO  
 DRAWN BY: BMD  
 APPROVED BY: ARO

CELL NO. 7


SHEET NO. 7




**RIGHT CELL WALL**  
 NOT TO SCALE



**LEFT CELL WALL**  
 NOT TO SCALE



**UPSTREAM WALL AND CEILING OF CELL**  
 NOT TO SCALE



**SPILLWAY DOWNSTREAM FACE AND BUTTRESSES**  
 NOT TO SCALE


NOT FOR CONSTRUCTION

F:\086\19 Jobs\19169.00 WB-OysterRiver-Mill Pond Dam Feasibility-MA\REPORTS\Dam Inspection 2021\Drawings\Crack Inspection Dwg\CELL 7.dwg


REVISIONS:

|  |  |
|--|--|
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |


PROJECT NO.: 19169.00  
 DATE: OCTOBER 2021  
 SCALE: NTS  
 DESIGNED BY: BMD  
 CHECKED BY: ARO  
 DRAWN BY: BMD  
 APPROVED BY: ARO




**RIGHT CELL WALL**  
 NOT TO SCALE



**LEFT CELL WALL**  
 NOT TO SCALE




**UPSTREAM WALL AND CEILING OF CELL**  
 NOT TO SCALE




**SPILLWAY DOWNSTREAM FACE AND BUTTRESSES**  
 NOT TO SCALE


F:\086\19 Jobs\19169.00 WB-OysterRiver-Mill Pond Dam Feasibility-MA\REPORTS\Dam Inspection 2021\Drawings\Crack Inspection Dwg\CELL 8.dwg




**RIGHT CELL WALL**  
 NOT TO SCALE



**LEFT CELL WALL**  
 NOT TO SCALE



**UPSTREAM WALL AND CEILING OF CELL**  
 NOT TO SCALE



**SPILLWAY DOWNSTREAM FACE AND BUTTRESSES**  
 NOT TO SCALE

REVISIONS:

| NO. | DATE | DESCRIPTION |
|-----|------|-------------|
|     |      |             |
|     |      |             |
|     |      |             |
|     |      |             |

PROJECT NO.: 19169.00  
 DATE: OCTOBER 2021  
 SCALE: NTS  
 DESIGNED BY: BMD  
 CHECKED BY: ARO  
 DRAWN BY: BMD  
 APPROVED BY: ARO

CELL NO. 9

SHEET NO.:

9

NOT FOR CONSTRUCTION



**APPENDIX B**  
**Photographs**  
*Mill Pond Dam*  
*Durham, NH*





Photo No. 1.: Overview of the downstream side of the dam.



Photo No. 3.: View of the spillway crest



Photo No. 2.: Overview of the upstream side of the dam.



Photo No. 4.: View of the left abutment



Photo No. 5.: Minor leakage between the left channel wall and the fish ladder wall.




Photo No. 7.: Overview of the downstream side of the spillway.



Photo No. 6.: View of the right spillway channel wall. Note scoured concrete behind the spillway crest.



Photo No. 8.: Close-up view and typical downstream face conditions of the spillway cells.



Photo No. 9.: Left interior wall



Photo No. 11.: Upstream sloped ceiling. Note location of delamination along repairs.



Photo No. 10.: Right wall. Note leakage along the interface between the ceiling and the right wall.



Photo No. 12.: Repair along the downstream sloped ceiling section (ceiling face No. 3). Note delamination above the repair with efflorescence staining.



Photo No. 13.: left Wall. Note spalling and cracking beneath the downstream end of the spillway.



Photo No. 15.: Right wall. Note 100% section loss beneath the downstream end of the spillway. The hole pictured has continued to deteriorate since the previous inspection.



Photo No. 14.: Delamination and concrete deterioration along the right (photo left) portion of the upstream sloped ceiling (ceiling face no. 5).



Photo No. 16.: Downstream sloped portion of the ceiling: Note delamination along the top of the concrete repair and cracking and efflorescence along the right side of the ceiling.



Photo No. 17.: Left Wall: Note concrete spalling on the downstream end of the wall beneath the spillway.



Photo No. 19.: Right wall. Note scour and spalling at the downstream end of the wall. Limited concrete deterioration was observed along ceiling face no. 5.



Photo No. 18.: Debonded rebar along the top of the rib between Cell 3 and Cell 4.



Photo No. 20.: Deterioration along the top of the concrete repair along downstream face of the ceiling (ceiling face No. 3).



Photo No. 21.: Left Wall. Note debonded rebar and spalling on the downstream end of the wall.



Photo No. 23.: Right wall. Note crack with 1/2" of left to right displacement.



Photo No. 22.: Overview of the downstream slope of the ceiling (ceiling face no. 3).



Photo No. 24.: Close-up view of the crack along the upstream side of right wall. Note iron oxide was previously observed within crack but not observed during this inspection.



Photo No. 25.: Left Wall. Note scour and light spalling along the downstream end of the wall and approximately 1-foot above the waterline at the time the photo was taken.



Photo No. 27.: Right Wall. Note debonded rebar and spalling at the downstream end of the wall.



Photo No. 26.: Downstream portions of the ceiling. Note minor map cracking along ceiling face no. 3.



Photo No. 28.: Downstream face of the cell. Note the exposed rebar extending from the top of the stem between Cell 5 and Cell 4 to the mid-height of the stem.





Photo No. 29.: Left Wall. Note efflorescent staining and cracking.



Photo No. 31.: Overview of the downstream face of the Cell.



Photo No. 30.: Right Wall. Concrete in fair condition.



Photo No. 32.: Section loss and debonded rebar along the top of the rib between Cell 6 and Cell 7.



Photo No. 33.: Left Wall. Note scour up to 1.25 inches deep along the bottom 5 inches of the wall.



Photo No. 35.: Close-up view of the top of the deterioration of the right wall. Note location of previously noted leakage not observed during this inspection.



Photo No. 34.: Right Wall. Note cracking and spalling throughout the right wall and the upstream slope of the right wall.



Photo No. 36.: Delamination, spalling, and efflorescence throughout the downstream sloped portion of the ceiling.



Photo No. 37.: Left Wall: Note repairs covered with timber falsework.



Photo No. 39.: Right wall



Photo No. 38.: Exposed deteriorated rebar near the top of the upstream portion of the ceiling.



Photo No. 40.: Exposed deteriorated rebar and concrete spall on the downstream sloped portion of the ceiling.



Photo No. 41.: Left Wall. Note evidence of poor concrete consolidation along the top of the wall at ceiling face no. 3 (circle). Previous location of iron oxide staining (arrow)



Photo No. 43.: Right wall. Note scour and concrete deterioration at the downstream end of the wall.



Photo No. 42.: Poor concrete consolidation at the downstream end of the left wall.



Photo No. 44.: Downstream face of Cell 9.



Photo No. 45.: Right abutment upstream of the low-level outlet.



Photo No. 47.: Top of the low-level outlet control structure and gate operators.



Photo No. 46.: Overview of the upstream side of the low-level outlets. Note concrete deterioration along the upstream face of the concrete wall.



Photo No. 48.: Downstream face of the low-level outlet structure. Note further concrete smalling noted when compared to 2019 inspection report.



Photo No. 49.: Leakage through the low-level outlet timber gates. Note concrete deterioration throughout the downstream wall.



Photo No. 51.: Overview of the fish ladder at the left abutment.



Photo No. 50.: Remnants of mill foundations downstream of the low-level outlet.



Photo No. 52.: Upstream end of the fish ladder.



Photo No. 53.: Overview of the top face of the fish ladder.



Photo No. 55.: Overview of the Reservoir.



Photo No. 54.: Scour hole at bottom of right fish ladder wall at the downstream channel. Note void was probed approximately 36 inches.



Photo No. 56.: Downstream area of the dam looking downstream at the bridge carrying Newmarket Road.

**APPENDIX C**  
**Previous Reports and References**  
*Mill Pond Dam*  
*Durham, NH*





## REFERENCES AND RESOURCES

The following reports were referenced during the preparation of this report:

1. “Feasibility Study – NHDES Dam #071.03 Oyster River Dam at Mill Pond”, prepared by VHB, dated November 2020.
2. “Mill Pond Dam – D071003, Hazard Classification Assessment”, New Hampshire Department of Environmental Services, dated April 17, 2020
3. “Mill Pond Dam – Visual Inspection Report”, prepared by Pare Corporation, dated March 2020.
4. “Mill Pond Dam (D71.03) Hazard Reclassification Analysis Memorandum”, prepared by Weston & Sampson, dated March 2, 2020
5. “Mill Pond Dam – D071003, Hazard Classification Assessment”, New Hampshire Department of Environmental Services, dated September 10, 2018.
6. “Dam Evaluation Report – Oyster River Dam”, Stephens Associates Consulting Engineers, dated March 17, 2009.
7. “Letter to Andrea Bodo”, New Hampshire Division of Historical Resources”, dated February 4, 2009.
8. “Site Inspection Form”, New Hampshire Department of Environmental Services, dated September 18, 2007.
9. “Dam Inspection Report”, GZA GeoEnvironmental, Inc, dated October 3, 2000.

The following were referenced during the completion of the visual inspection and preparation of this report and the development of the recommendations presented herein:

1. “Design of Small Dams”, United States Department of the Interior Bureau of Reclamation, 1987.
2. “ER 110-2-106 - Recommended Guidelines for Safety Inspection of Dams”, Department of the Army, September 26, 1979.
3. “Guidelines for Reporting the Performance of Dams” National Performance of Dams Program, August 1994.

The following provides an abbreviated list of resources for dam owners to locate additional information pertaining to dam safety, regulations, maintenance, operations, and other information relevant to the ownership responsibilities associated with their dam.

1. NHDES Dam Bureau Website:  
<https://www.des.nh.gov/organization/divisions/water/dam/index.htm>
2. “Dam Owner’s Guide To Plant Impact On Earthen Dams” *FEMA L-263, September 2005*
3. “Technical Manual for Dam Owners: Impacts of Plants on Earthen Dams” *FEMA 534, September 2005*
4. “Dam Safety: An Owners Guidance Manual” *FEMA 145, December 1986*
5. Association of Dam Safety Officials – Website: [www.asdso.org/](http://www.asdso.org/)
6. “Dam Ownership – Responsibility and Liability”, ASDSO



**APPENDIX D**  
**Common Dam Safety Definitions**  
*Mill Pond Dam*  
*Durham, NH*



## COMMON DAM SAFETY DEFINITIONS

For a comprehensive list of dam engineering terminology and definitions refer to State of New Hampshire Env-Wr 100-700 Dam Rules, or other reference published by FERC, Dept. of the Interior Bureau of Reclamation, or FEMA.

### Orientation

Upstream – Shall mean the side of the dam that borders the impoundment.

Downstream – Shall mean the high side of the dam, the side opposite the upstream side.

Right – Shall mean the area to the right when looking in the downstream direction.

Left – Shall mean the area to the left when looking in the downstream direction.

### Dam Components

Dam – Shall mean any artificial barrier, including appurtenant works, which impounds or diverts water.

Embankment – Shall mean the fill material, usually earth or rock, placed with sloping sides, such that it forms a permanent barrier that impounds water.

Crest – Shall mean the top of the dam, usually provides a road or path across the dam.

Abutment – Shall mean that part of a valley side against which a dam is constructed. An artificial abutment is sometimes constructed as a concrete gravity section, to take the thrust of an arch dam where there is no suitable natural abutment.

Appurtenant Works – Shall mean structures, either in dams or separate therefrom, including but not be limited to, spillways; reservoirs and their rims; low level outlet works; and water conduits including tunnels, pipelines, or penstocks, either through the dams or their abutments.

Spillway – Shall mean a structure over or through which water flows are discharged. If the flow is controlled by gates or boards, it is a controlled spillway; if the fixed elevation of the spillway crest controls the level of the impoundment, it is an uncontrolled spillway.

### Hazard Classification

High Hazard – means a dam where failure or misoperation will result in probable loss of human life.

Significant Hazard – means a dam where failure or misoperation results in no probable loss of human life but can cause major economic loss to structures or property, structural damage to a class I or class II road which could render the road impassable or otherwise interrupt public safety services, or major environmental or public health losses.

Low Hazard – means a dam where failure or misoperation results in no probable loss of human life, low economic losses, structural damage to a town or city road or private road accessing property other than the dam owner's which could render the road impassable or otherwise interrupt public safety services, the release of liquid industrial, agricultural, or commercial wastes, septage, or contaminated sediment if the storage capacity is less than 2 acre-feet and is located more than 250 feet from a water body or water course, Reversible environmental losses to environmentally-sensitive sites.



## **General**

EAP – Emergency Action Plan – Shall mean a predetermined (and properly documented) plan of action to be taken to reduce the potential for property damage and/or loss of life in an area affected by an impending dam failure.

O&M Manual – Operations and Maintenance Manual; Document identifying routine maintenance and operational procedures under normal and storm conditions.

Normal Pool – Shall mean the elevation of the impoundment during normal operating conditions.

Acre-foot – Shall mean a unit of volumetric measure that would cover one acre to a depth of one foot. It is equal to 43,560 cubic feet. One million U.S. gallons = 3.068 acre feet.

Height of Dam– means the vertical distance from the lowest point of natural ground on the downstream side of the dam to the highest part of the dam which would impound water.

Hydraulic Height – means the height to which water rises behind a dam and the difference between the lowest point in the original streambed at the axis of the dam and the maximum controllable water surface.

Maximum Water Storage Elevation – means the maximum elevation of water surface which can be contained by the dam without overtopping the embankment section.

Spillway Design Flood (SDF) – Shall mean the flood used in the design of a dam and its appurtenant works particularly for sizing the spillway and outlet works, and for determining maximum temporary storage and height of dam requirements.

Maximum Storage Capacity – The volume of water contained in the impoundment at maximum water storage elevation.

Normal Storage Capacity – The volume of water contained in the impoundment at normal water storage elevation.

## **Condition Rating**

Unsafe – Means the condition of a regulated dam, as determined by the Director, is such that an unreasonable risk of failure exists that will result in a probable loss of human life or major economic loss. Among the conditions that would result in this determination are: excessive vegetation that does not allow the Director to perform a complete visual inspection of a dam, excessive seepage or piping, significant erosion problems, inadequate spillway capacity, inadequate capacity and/or condition of control structure(s) or serious structural deficiencies, including movement of the structure or major cracking.

Poor – A component that has deteriorated beyond a maintenance issue and requires repair.; the component no longer functions as it was originally intended.

Fair – Means a component that requires maintenance

Good – Meeting minimum guidelines where no irregularities are observed, and the component appears to be maintained properly.



**APPENDIX E**  
**Visual Dam Inspection Limitations**  
*Mill Pond Dam*  
*Durham, NH*



## **VISUAL DAM INSPECTION LIMITATIONS**

### **Visual Inspection**

1. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigations and analyses involving topographic mapping, subsurface investigations, testing and detailed computational evaluations are beyond the scope of this report.
2. In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection, along with data available to the inspection team.
3. In cases where an impoundment is lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions, which might otherwise be detectable if inspected under the normal operating environment of the structure.
4. It is critical to note that the condition of the dam is evolutionary in nature and depends on numerous and constantly changing internal and external conditions. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

### **Use of Report**

5. The applicability of environmental permits needs to be determined prior to undertaking maintenance activities that may occur within resource areas under the jurisdiction of any regulatory agency.
6. This report has been prepared for the exclusive use of the Town of Durham for specific application to the referenced dam site in accordance with generally accepted engineering practices. No other warranty, expressed or implied, is made.
7. This report has been prepared for this project by Pare. This report is for preliminary evaluation purposes only and is not necessarily sufficient to support design of repairs or recommendations or to prepare an accurate bid.